

11/25/07 11:2

F A X



MONTGOMERY WATSON

2100 Corporate Drive  
Addison, IL 60101

Date: 25-Nov-97

Tel: 630 691-5020  
Fax: 630 691-5133

To: Sheri Bianchin  
Luanne Vanderpool  
Steve Mrkvika  
Gary Taylor

Fax No.: (312) 886-4071  
Fax No.: (312) 886-4071  
Fax No.: (312) 346-4781  
Fax No.: (317) 308-3063

CC:

Fax No.:  
Fax No.:

From: Pete Vagt

Subject: Well Abandonment SOPs

COMMENTS

Attached are copies of two Well Abandonment SOPs

One is the revised SOP for the abandonment of the ACS production Wells. Specifically, we have changed Section F on Page 13 and 14.

The other is the new SOP for abandoning and replacing MW9.

We would like to schedule these activities to occur in December, if the SOPs can be approved in that time frame. Please call me if I can provide clarification on any of the procedures or issues.

Pete

US EPA RECORDS CENTER REGION 5



464646

If you do not receive all pages, or if there are any problems with this transmission, please call (630) 691-5000. Operator: No. of pages including cover: